
LD90S Rain Test Report

Data: 2013-08-12



Test result:1.After steep 72H, blow dry the water on the lens surface with air pressure gun.Remove the lens and check the aluminum plate surface, no water seepage phenomenon.Light up the test, led light source are luminous normally.

测试员: 责任人: 审核:
